

---

# NOTICE TO MARINERS

---

No. H. 04/2019

## HUMBER APPROACHES

### SPURN LIGHT FLOAT – RETURNED TO STATION

**NOTICE IS HEREBY GIVEN** that following the completion of routine maintenance, the Spurn Light Float (Catamaran) has been returned to its' original charted position and the temporary light float removed.

The light characteristics of the float remain unchanged and the Racon (M) has been reinstated.

Position: Latitude 53° 33.417' N, Longitude 000° 14.148' E

Characteristics: Q (3).10s Racon (M)

**MARINERS ARE ADVISED** that Notice to Mariners No.H.143/2018 is hereby cancelled.

**CAPT. A. FIRMAN  
HARBOUR MASTER, HUMBER**

4 January 2019

#### THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

[www.humber.com](http://www.humber.com)