
NOTICE TO MARINERS

No. H. 09/2018

HUMBER APPROACHES

EON HUMBER GATEWAY WIND FARM PROJECT

MARINERS ARE ADVISED that the Aviation and Transition Piece (TP) lights at the EON Humber Gateway Wind Farm Project are inoperative in the following positions:-

WTG	Position	Defect
A06	53 39.1969N 000 15.4559E	TP lights inoperative
A12	53 36.9627N 000 16.3045E	1 Aviation light inoperative
C06	53 38.7901N 000 16.5107E	TP Lights inoperative
D07	53 38.4273N 000 17.1793E	TP lights inoperative
E04	53 39.3418N 000 17.2832E	TP lights inoperative
E08	53 38.0644N 000 17.8476E	South side TP Lights inoperative
F08	53 38.0203N 000 18.3752E	TP lights inoperative
F09	53 37.7030N 000 18.1109E	1 Aviation light inoperative
G07	53 38.2955N 000 18.7615E	TP lights inoperative
G08	53 37.9788N 000 18.8992E	TP lights inoperative
		1 Aviation light inoperative
H01	53 40.1670N 000 18.4417E	Aviation lights inoperative
H07	53 38.2518N 000 19.2883E	TP lights inoperative
I05	53 38.8464N 000 19.5334E	TP lights inoperative
I06	53 38.5272N 000 19.6847E	TP lights inoperative
		1 Aviation light inoperative

MARINERS ARE WARNED to navigate with caution in the area.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

12th January 2018

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com