

---

# **NOTICE TO MARINERS**

---

**No. H. 149/2016**

## **U P P E R H U M B E R**

### **SHOAL WATER**

**MARINERS ARE WARNED** that surveys carried out on the 1<sup>st</sup> and 2<sup>nd</sup> December 2016 show:-

- 1) A least depth of 0.2 metres below Chart Datum exists close South of the ships course 260 metres upstream of the Upper Whitton Light Float.

Deeper water exists on and to the North of the ships course in this vicinity

- 2) A least depth of 0.1 metres below Chart Datum exists close North of the ships course 400 metres upstream of the No. 34 Light Buoy.

Deeper water exists on and to the South of the ships course in this vicinity.

**MARINERS ARE ADVISED** that 0.2 metres below Chart Datum should be used for passage planning purposes and the shoal water referred to in Notice to Mariners No. H.140/2016 is no longer valid.

**CAPT. A. FIRMAN  
HARBOUR MASTER, HUMBER**

2<sup>nd</sup> December 2016