

NOTICE TO MARINERS

No. H. 46/2018

U P P E R H U M B E R

SHOAL WATER

MARINERS ARE WARNED that a survey carried out on the 19th March 2018 shows the following: -

- 1) A least depth of 0.5 metres **ABOVE** Chart Datum exists North of the ships course 310 metres downstream of the Lower Whitton Light Float.

Deeper water exists on the ships course in this vicinity.

- 2) A least depth of 0.5 metres below Chart Datum exists close North of the ships course 60 metres downstream of the Cappers West Light Float.

Deeper water exists on the ships course in this vicinity.

- 3) A least depth of 0.1 metres **ABOVE** Chart Datum exists close South of the ships course in the vicinity of the No. 32B Light Float.

Deeper water exists to the North of the ships course in this vicinity.

- 4) A least depth of 0.2 metres below Chart Datum exists on the ships course 185 metres upstream of the No. 32B Light Float.

Deeper water exists to the North of the ships course in this vicinity.

- 5) A least depth of 0.2 metres **ABOVE** Chart Datum exists North of the ships course 130 metres downstream of the No. 34 Light Buoy.

Deeper water exists on the ships course in this vicinity.

MARINERS ARE ADVISED that 0.1 metres **ABOVE** Chart Datum should be used for passage planning purposes and the shoal water referred to in Notice to Mariners No. H. 37/2018 is no longer valid.

CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER

19th March 2018

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com