

# NOTICE TO MARINERS

**No. H. 74/2018**


## **HUMBER APPROACHES**

### **HORNSEA WIND FARM – CABLE LAYING OPERATIONS – INTERTIDAL AREA SUBMERGED PILES**

**MARINERS ARE WARNED** that partially submerged piles indicated below are in position within the Hornsea Wind Farm onshore intertidal works precautionary area as indicated on Notice To Mariners H. 53/2018.

The piles have been marked on the River Humber with orange buoys to designate the most easterly pile and continue in a westerly direction to the western edge of the cable corridor as shown below.

	Latitude	Longitude
Buoy 1	53° 30.83' N	0° 05.68' E
Buoy 2	53° 30.86' N	0° 05.72' E
Buoy 3	53° 30.88' N	0° 05.75' E
Buoy 4	53° 30.92' N	0° 05.82' E



**MARINERS ARE REQUESTED** not to navigate within the 100m zone either side of the works in the onshore intertidal area, unless for the purpose of; or in connection with; the construction, maintenance or operation of the authorised works. Additionally mariners are advised to pass at a reduced speed to avoid creating a wash.

**CAPT. A FIRMAN  
HARBOUR MASTER, HUMBER**

10 May 2018

**THE INTERNET**

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

[www.humber.com](http://www.humber.com)