
NOTICE TO MARINERS

No. H. 78/2018

R I V E R H U M B E R

HULL – KING GEORGE DOCK REPAIR WORKS

MARINERS ARE WARNED that due to damaged fenders, the Eastern Approach Jetty to King George Dock, Hull **SHOULD NOT BE USED**.

MARINERS ARE REQUESTED to make any approach to King George Dock via the Western Approach Jetty.

MARINERS ARE FURTHER REQUESTED to contact the Assistant Dock Master on VHF CH11 prior to transiting the lock.

CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER

14th May 2018

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.
www.humber.com