

---

# NOTICE TO MARINERS

---

No. H. 85/2018  
**U P P E R H U M B E R**  
**S H O A L W A T E R**

**MARINERS ARE WARNED** that surveys carried out on the 17<sup>th</sup>, 18<sup>th</sup> and 23<sup>rd</sup> of May 2018 show the following: -

- 1) A least depth of 0.4 metres **ABOVE** Chart Datum exists close North of the ships course 331 metres downstream of the Lower Whitton Light Float.

Deeper water exists on and to the South of the ships course in this vicinity.

- 2) A least depth of 0.1 metres below Chart Datum exists South of the ships course 212 metres downstream of the No. 33A Light Buoy.

Deeper water exists on the ships course in this vicinity.

- 3) A least depth of 0.7 metres **ABOVE** Chart Datum exists close South of the ships course 110 metres upstream of the No. 33A Light Buoy.

Deeper water exists on the ships course in this vicinity

- 4) A least depth of 0.1 metres **ABOVE** Chart Datum exists North of the ships course 170 metres upstream of the No. 32C Light Buoy.

Deeper water exists on the ships course in this vicinity.

**MARINERS ARE ADVISED** that 0.7 metres **ABOVE** Chart Datum should be used for passage planning purposes and the shoal waters referred to in Notice to Mariners No. H. 82/2018 are no longer valid.

**CAPT. A. FIRMAN**  
**HARBOUR MASTER, HUMBER**

24<sup>th</sup> May 2018

**THE INTERNET**

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

[www.humber.com](http://www.humber.com)