
NOTICE TO MARINERS

No. H. 66/2024

HUMBER APPROACHES

SPURN LIGHT FLOAT – RETURNED TO STATION FOLLOWING MAINTENANCE

MARINERS ARE ADVISED that the original Spurn Light Float has been returned to station, following routine maintenance, to its original charted position.

The mono-hull Light Float exhibits the following characteristics:

Latitude: 53° 33.417' N Longitude: 0° 14.148' E (WGS 84)

Characteristics: Q(3)10s

Racon: (M)

MARINERS ARE FURTHER ADVISED that Notice to Mariners No. H.120/2023 is hereby cancelled.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

5th June 2024

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com