
NOTICE TO MARINERS

No. H. 84/2023

RIVER HUMBER

No. 7 MIDDLE LIGHT FLOAT TEMPORARY REPLACEMENT

MARINERS ARE ADVISED that the No. 7 Middle Light Float has been removed from station for routine maintenance. Until further notice, a South Cardinal Light Buoy displaying the same characteristics is being used as a temporary replacement in its charted position (see details below):

- South Cardinal Light Buoy
- Light Characteristics – VQ(6)+LFl.10s
- Position – 53° 35.732' N, 0° 01.503' W (WGS84)
- No Name Board is Present

MARINERS ARE ADVISED to navigate with caution in this vicinity.

CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER

23rd June 2023

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com