

---

# NOTICE TO MARINERS

---

**No. H. 13/2026**

## HUMBER APPROACHES

### SPURN LIGHT FLOAT – RACON INOPERATIVE

**MARINERS ARE WARNED** that the Racon on the Spurn Light Float is inoperative in position:

Latitude: 53° 33.417' N    Longitude: 0° 14.148' E

Characteristics: Q(3)10s                  Racon(M)

This will be restored as soon as circumstances permit.

**MARINERS ARE ADVISED** to exercise care and caution when navigating in this vicinity.

**CAPT. A. FIRMAN  
HARBOUR MASTER, HUMBER**

22<sup>nd</sup> January 2026

#### THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.