
NOTICE TO MARINERS

No. H. 15/2018

U P P E R H U M B E R

MOVES OF FLOATING MARKS AND SHOAL WATER

NOTICE IS HEREBY GIVEN that it is proposed on Thursday 25th January 2018 (or as soon after as circumstances permit) to move: -

- 1) The No. 33A Light Float to a position 041° T., 746 metres from the Whitton Ness Beacon.

Latitude 53° 43.162' N, Longitude 0° 36.200' W (WGS 84)

(153 metres North East of its current position)

- 2) The Upper Whitton Light Float to a position 305° T., 1552 metres from Whitton Ness Beacon.

Latitude 53° 43.340' N, Longitude 0° 37.793' W (WGS 84)

(83 metres North West of its current position)

- 3) The No. 32C Light Buoy to a position 282° T., 2150 metres from the Whitton Ness Beacon.

Latitude 53° 43.097' N, Longitude 0° 38.554' W (WGS 84)

(273 metres North East of its current position)

The No. 33A Light Float will then bear 341° T., 775 metres from the Middle Whitton Light Float and 108° T., 893 metres from the No. 32B Light Float.

The Upper Whitton Light Float will then bear 274° T., 902 metres from the No. 32B Light Float.

The No. 32C Light Buoy will then bear 242° T., 950 metres from the new position of the Upper Whitton Light Float and 032° T., 1590 metres from the No. 40 East Walker Dyke Light.

MARINERS ARE WARNED that on completion of the above moves, the following shoal water will exist: -

- 1) A least depth of 0.8 metres **ABOVE** Chart Datum exists close North of the ships course 320 metres downstream of the Lower Whitton Light Float.

Deeper water exists on the ships course in this vicinity.

- 2) A least depth of 0.2 metres **ABOVE** Chart Datum exists close North of the ships course 320 metres downstream of the No. 33 Light Float.

Deeper water exists on and to the South of the ships course in this vicinity.

- 3) A least depth of 0.2 metres below Chart Datum exists in the navigable channel from 140 to 630 metres upstream of the No. 32C Light Buoy.

- 4) A least depth of 0.1 metres **ABOVE** Chart Datum exists North of the ships course 715 metres upstream of the No. 32C Light Buoy.

Deeper water exists on the ships course in this vicinity.

MARINERS ARE ADVISED that on completion of the above moves 0.1 metres below Chart Datum should be used for passage planning purposes and Notice to Mariners No. H. 14/2018 will be cancelled.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

24th January 2018

[THE INTERNET](#)

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com