

---

# NOTICE TO MARINERS

---

No. H. 60/2017

## RIVER HUMBER

### HULL ROADS – WEST MIDDLE – SHOAL WATER

**MARINERS ARE WARNED** that a survey carried out on the 18<sup>th</sup> May 2017 shows the following:

- 1) A least depth of 3.8 metres below Chart Datum exists on the Southern edge of the channel from 250 metres upstream to 530 metres downstream of the No. 26 Upper West Middle Light Buoy.

Deeper water exists to the North in this vicinity.

- 2) Depths of between 3.8 metres and 5.5 metres below Chart Datum have encroached up to 225 metres into the Southern edge of the channel from 180 metres upstream of the No. 24 Lower West Middle Light Buoy to the No. 26A Light Buoy.

Deeper water exists to the North in this vicinity.

**MARINERS ARE ADVISED** that Notice to Mariners No. H. 37/2017 is hereby cancelled.

**CAPT. A FIRMAN**  
**HARBOUR MASTER, HUMBER**

18<sup>th</sup> May 2017

**LOCAL NOTICE TO MARINERS FOR 2012, 2014, 2015, 2016 & 2017 CURRENTLY IN FORCE:**

H. 15/2012, H. 50/2014, H. 42/2015, H. 61/2016, H. 74/2016, H. 78/2016, H. 144/2016, H. 161/2016, H. 02/2017, H. 06/2017, H. 09/2017, H. 11/2017, H. 22/2017, **H. 24/2017**, H. 28/2017, H. 31/2017, **H. 34/2017**, **H. 39/2017**, **H. 41/2017**, **H. 43/2017**, H. 44/2017, **H. 47/2017**, H. 49/2017, H. 50/2017, H. 51/2017, H. 53/2017, **H. 54/2017**, H. 55/2017, H. 57/2017, H. 58/2017, H. 59/2017, H. 60/2017,

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

[www.humber.com](http://www.humber.com)