

---

# **NOTICE TO MARINERS**

---

**No. H. 79/2015**

## **R I V E R H U M B E R**

### **HUMBER APPROACHES – UNDERWATER OBSTRUCTION**

**MARINERS ARE WARNED** that a survey carried out in the Humber Inner Approaches shows the following:-

An obstruction with a least depth of 14.5 metres below Chart Datum exists 330 metres South West of the No.3 Chequer South Cardinal Buoy in position:

Latitude 53° 32.930' N      Longitude 000° 10.435' E (WGS 84)

**MARINERS ARE ADVISED** to navigate with caution in this area.

**CAPT. A. FIRMAN  
HARBOUR MASTER, HUMBER**

30<sup>th</sup> July 2015

#### **THE INTERNET**

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

[www.humber.com](http://www.humber.com)