
NOTICE TO MARINERS

No. H. 03/2017

U P P E R H U M B E R

S H O A L W A T E R

MARINERS ARE WARNED that surveys carried out on the 3rd and 4th January 2017 show: -

- 1) A least depth of 0.4 metres below Chart Datum exists close North of the ships course 250 metres downstream of the Lower Whitton Light Float.

Deeper water exists on the ships course in this vicinity.

- 2) A least depth of 0 metres at Chart Datum exists close East of the ships course in the vicinity of the No. 33 Light Float.

Deeper water exists on and to the West of the ships course in this vicinity.

- 3) A least depth of 0.1 metres **ABOVE** Chart Datum exists close South of the ships course 310 metres upstream of the No. 32B Light Float.

Deeper water exists on and to the North of the ships course in this vicinity.

- 4) A least depth of 0.2 metres below Chart Datum exists close South of the ships course between 210 metres and 300 metres upstream of the No. 32C Light Buoy.

Deeper water exists on the ships course in this vicinity.

- 5) A least depth of 0.1 metres below Chart Datum exists close South of the ships course 220 metres upstream of the No. 34 Light Buoy.

Deeper water exists on the ships course in this vicinity.

MARINERS ARE ADVISED that 0 metres at Chart Datum should be used for passage planning purposes and the shoal waters referred to in Notice to Mariners No. H. 162/2016 are hereby cancelled.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

4th January 2017

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com