
NOTICE TO MARINERS

No. H. 03/2019

RIVER HUMBER

HESSLE SANDS - SHOAL WATER

MARINERS ARE WARNED that surveys carried out on the 2nd and 3rd of January 2019 show the following: -

- 1) A least depth of 0.1 metres below Chart Datum exists close North of the ships course from 350 metres to 555 metres downstream of the No. 23 Light Buoy.

Deeper water exists on and to the South of the ships course in this vicinity.

- 2) A least depth of 0.2 metres below Chart Datum exists close North of the ships course from 75 metres to 230 metres upstream of the No. 23 Light Buoy.

Deeper water exists on and to the South of the ships course in this vicinity.

MARINERS ARE ADVISED that 0 metres at Chart Datum should be used for passage planning purposes and shoal water referred to in Notice to Mariners No. H. 188/2018 is no longer valid.

**CAPT. A FIRMAN
HARBOUR MASTER, HUMBER**

3rd January 2019

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.
www.humber.com