

---

# NOTICE TO MARINERS

---

No. H. 07/2018

## U P P E R H U M B E R

### MOVE AND REMOVAL OF FLOATING MARKS – ALTERATION OF SHIPS COURSE AND SHOAL WATER

**MARINERS ARE WARNED** that due to unforeseen circumstances, the moves of floating marks detailed in Notice to Mariners No. H. 06/2018 have not taken place.

**NOTICE IS HEREBY GIVEN** that with immediate effect, the arrangement of navigational marks (working upstream) are as follow: -

- 1) The Upper Whitton Light Float remains in its' previously charted position.  
Latitude 53° 43.301' N, Longitude 0° 37.757' W (WGS 84)
- 2) The No. 32C Light Buoy has been moved to a position 278° T., 2375 metres from the Whitton Ness Beacon.  
Latitude 53° 43.036' N, Longitude 0° 38.779' W (WGS 84)  
(41 metres East of its current position)

The No. 32C Light Buoy now bears 246° T., 1228 metres from the Upper Whitton Light Float.

- 3) The No. 34 Light Buoy has been removed from service until further notice, in order to carry out essential maintenance.
- 4) The No. 40 East Walker Dyke Light has been reinstated into the ships course. Mariners should proceed directly to it from the No. 32C Light Buoy before continuing to the No. 42 West Walker Dyke Light.

**MARINERS ARE FURTHER WARNED** that the following shoal water exists: -

- 1) A least depth of 0.8 metres **ABOVE** Chart Datum exists close North of the ships course 310 metres downstream of the Lower Whitton Light Float.

Deeper water exists on the ships course in this vicinity.

- 2) A least depth of 0.2 metres below Chart Datum exists South of the ships course from 55 metres to 410 metres upstream of the No. 32C Light Buoy.

Deeper water exists on the ships course in this vicinity.

- 3) A least depth of 0.3 metres below Chart Datum exists North of the ships course from 550 to 1060 metres downstream of the No. 40 East Walker Dyke Light.

Deeper water exists on the ships course in this vicinity.

**MARINERS ARE ADVISED** that 0.1 metres below Chart Datum should be used for passage planning purposes and Notice to Mariners No. H. 05/2018 and No. H. 06/2018 are hereby cancelled.

**CAPT. A. FIRMAN  
HARBOUR MASTER, HUMBER**

9<sup>th</sup> January 2018

[THE INTERNET](#)

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

[www.humber.com](http://www.humber.com)