
NOTICE TO MARINERS

No. H. 08/2016

HUMBER APPROACHES

HUMBER GATEWAY WINDFARM – REMOVAL OF TEMPORARY CARDINAL MARKS AND ESTABLISHMENT OF NAVIGATION MARK

MARINERS ARE ADVISED that the following temporary Cardinal buoys marking the extent of the Humber Gateway wind farm construction area have been permanently removed:

Buoy 1	West Cardinal Lighted Buoy (N)	(V Q (9) 10s)	Lat 53° 39.9'N.	Long 000° 14.2'E.
Buoy 2	West Cardinal Lighted Buoy (S)	(Q (9) 15s)	Lat 53° 37.0'N.	Long 000° 15.6'E.
Buoy 3	South Cardinal Lighted Buoy	(Q (6) + L Fl 15s)	Lat 53° 36.5'N.	Long 000° 17.4'E.
Buoy 4	East Cardinal Lighted Buoy (S)	(Q (3) 10s)	Lat 53° 38.4'N.	Long 000° 20.1'E.
Buoy 5	East Cardinal Lighted Buoy (N)	(V Q (3) 5s)	Lat 53° 40.3'N.	Long 000° 20.1'E.

MARINERS ARE FURTHER ADVISED that a permanent East Cardinal buoy “East 2” has been deployed to mark the North Eastern extremity of the wind farm:

East Cardinal Lighted Buoy “East 2”	(V Q (3) 5s)	Lat 53° 40.1'N.	Long 000° 20.1'E.
-------------------------------------	--------------	-----------------	-------------------

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

22 January 2016

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com