
NOTICE TO MARINERS

No. H. 08/2019

U P P E R H U M B E R
S H O A L W A T E R

MARINERS ARE WARNED that surveys carried out on the 8th and 9th January 2019 show the following: -

- 1) A least depth of 0.1 metre **ABOVE** Chart Datum exists close North of the ships course 420 metres downstream of the Lower Whitton Light Float.
Deeper water exists on and to the South of the ships course in this vicinity.
- 2) A least depth of 0.1 metres **ABOVE** Chart Datum exists North of the ships course 360 metres downstream of the No. 33 Light Float.
Deeper water exists on and to the South of the ships course in this vicinity.
- 3) A least depth of 0.5 metres below Chart Datum exists close South of the ships course in the vicinity of the Middle Whitton Light Float.
Deeper water exists on and to the North of the ships course in this vicinity.
- 4) A least depth of 0.5 metres below Chart Datum exists close South of the ships course in the vicinity of the Upper Whitton Light Float.
Deeper water exists on and to the North of the ships course in this vicinity.
- 5) A least depth of 0.4 metres **ABOVE** Chart Datum exists North of the ships course 115 metres downstream of the No. 34 Light Buoy.
Deeper water exists on the ships course in this vicinity.
- 6) A least depth of 0.1 metres **ABOVE** Chart Datum exists North of the ships course 395 metres upstream of the No. 40 East Walker Dyke Light.
Deeper water exists on the ships course in this vicinity.

MARINERS ARE ADVISED that 0 metres at Chart Datum should be used for passage planning purposes and that Notice to Mariners No. H. 06/2019 is hereby cancelled.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

9th January 2019

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com