
NOTICE TO MARINERS

No. H. 102/2018

RIVER HUMBER

HESSLE SAND - SHOAL WATER

MARINERS ARE WARNED that a survey carried out on the 21st June 2018 shows the following: -

A least depth of 0.1 metres below Chart Datum exists close North of the ships course in the vicinity of the No. 23 Light Buoy.

Deeper water exists to the South of the ships course in this vicinity.

MARINERS ARE ADVISED that 0.1 metres below Chart Datum should be used for passage planning and the shoal water referred to in Notice to Mariners No. H. 92/2018 is no longer valid.

**CAPT. A FIRMAN
HARBOUR MASTER, HUMBER**

22nd June 2018

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com