
NOTICE TO MARINERS

No. H. 104/2017

RIVER HUMBER

HESSLE SAND – SHOAL WATER

MARINERS ARE WARNED that a survey carried out on the 15th August 2017 shows the following:

- 1) A least depth of 0.3 metres below Chart Datum exists in the navigable channel from 120 metres to 410 metres downstream of the No. 23 Light Buoy.
- 2) A least depth of 0.1 metres below Chart Datum exists North of the ships course 300 metres upstream of the No. 23 Light Buoy.

Deeper water exists on and to the South of the ships course in this vicinity.

MARINERS ARE ADVISED that 0 metres at Chart Datum should be used for passage planning purposes and the shoal water referred to in Notice to Mariners No. H. 88/2017 is no longer valid.

**CAPT. A FIRMAN
HARBOUR MASTER, HUMBER**

16th August 2017

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com