
NOTICE TO MARINERS

No. H. 108/2018

U P P E R H U M B E R

S H O A L W A T E R

MARINERS ARE WARNED that surveys carried out on the 2nd and 3rd July 2018 show the following: -

- 1) A least depth of 0.6 metres **ABOVE** Chart Datum exists close North of the ships course 320 metres downstream of the Lower Whitton Light Float.

Deeper water exists on and to the South of the ships course in this vicinity.

- 2) A least depth of 0.3 metres **ABOVE** Chart Datum exists close South of the ships course 207 metres downstream of the No. 33A Light Float.

Deeper water exists on the ships course in this vicinity.

- 3) A least depth of 0.5 metres **ABOVE** Chart Datum exists North of the ships course 159 metres upstream of the No. 32C Light Buoy.

Deeper water exists on the ships course in this vicinity.

MARINERS ARE ADVISED that 0.3 metres **ABOVE** Chart Datum should be used for passage planning purposes and Notice to Mariners No. H. 107/2018 is hereby cancelled.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

3rd July 2018

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com