
NOTICE TO MARINERS

No. H. 111/2016

R I V E R H U M B E R

SKITTER CHANNEL - MOVE OF FLOATING MARK AND MONITORING BUOY

NOTICE IS HEREBY GIVEN that it is proposed on Wednesday 7th September 2016 (or as soon after as circumstances permit) to move:-

- 1) The No. 21A Light Buoy to a position:

Latitude 53° 43.785' N, Longitude 0° 16.491' W (WGS 84)

(184 metres North North West of its current position).

- 2) The OSIL Monitoring Buoy (NTM No. H. 21/2015):

Latitude 53° 43.801' N, Longitude 0° 17.218' W (WGS 84)

(179 metres West North West of its current position).

MARINERS ARE WARNED that on completion of the above moves depths of at least 1.0 metre below Chart Datum will exist throughout the Skitter Channel.

MARINERS ARE ADVISED that on completion of the above moves the ships course will traverse the southern extension of the Hook Deposit ground. Therefore, no dredge material should be deposited South of the new position of the No. 21A Light Buoy and further monitoring surveys will be conducted in the area.

MARINERS ARE FURTHER ADVISED that on completion of the above moves Notice to Mariners No. H.109/2016 will be cancelled.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

6th September 2016

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com