

---

# **NOTICE TO MARINERS**

---

**No. H. 12/2017**

## **RIVER HUMBER**

### **HULL ROADS – WEST MIDDLE - SHOAL WATER**

**MARINERS ARE WARNED** that surveys carried out on the 19<sup>th</sup> and 24<sup>th</sup> January 2017 show the following: -

- 1) A least depth of 3.7 metres below Chart Datum exists on the Southern edge of the channel 30 metres downstream of the No. 26A Light Buoy.

Deeper water exists to the North in this vicinity.

- 2) Depths of between 3.7 metres and 5.5 metres below Chart Datum have encroached up to 175 metres into the Southern edge of the channel from 135 metres upstream of the No. 24 Lower West Middle Light Buoy to 375 metres downstream of the No. 26A Light Buoy.

Deeper water exists to the North in this vicinity.

**MARINERS ARE ADVISED** that Notice to Mariners No. H. 146/2016 is hereby cancelled.

**CAPT. A. FIRMAN  
HARBOUR MASTER, HUMBER**

25<sup>th</sup> January 2017

**THE INTERNET**

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.  
[www.humber.com](http://www.humber.com)