

---

# NOTICE TO MARINERS

---

**No. H. 120/2016**

## RIVER HUMBER

### HULL ROADS – EAST MIDDLE - SHOAL WATER

**MARINERS ARE WARNED** that a survey carried out on the 29<sup>th</sup> September 2016 shows the following: -

- 1) A least depth of 2.7 metres below Chart Datum exists on the Southern edge of the channel 200 metres upstream of the East Middle Light Buoy.

Deeper water exists to the North in this vicinity.

- 2) Depths of between 2.7 metres and 5.5 metres below Chart Datum have encroached up to 70 metres into the Southern edge of the channel from 180 metres downstream of the No. 24 Lower West Middle Light Buoy to 375 metres downstream of the East Middle Light Buoy.

Deeper water exists to the North in this vicinity.

**MARINERS ARE ADVISED** that Notice to Mariners No. H. 87/2016 is hereby cancelled.

**CAPT. A. FIRMAN  
HARBOUR MASTER, HUMBER**

30<sup>th</sup> September 2016

**LOCAL NOTICE TO MARINERS FOR 2012, 2014, 2015 & 2016 CURRENTLY IN FORCE:**

H. 15/2012, H. 07/2014, H. 50/2014, H. 42/2015, H. 54/2015, H. 78/2015, H. 106/2015, H. 110/2015, H. 113/2015, H. 114/2015, H. 116/2015, H. 119/2015, H. 132/2015, H. 02/2016, H. 08/2016, H. 34/2016, H. 58/2016, H. 61/2016, H. 71/2016, H. 74/2016, H. 76/2016, **H. 77/2016, H. 89/2016** H. 90/2016, H.91/2016, **H.93/2016, H.94/2016**, H.96/2016, H.97/2016, H.98/2016, H.99/2016, H.105/2016, H.106/2016, **H.108/2016, H.109/2016**, H.110/2016, H.111/2016, H.114/2016, H.115/2016, **H.118/2016**, H.119/2016, H.120/2016

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

[www.humber.com](http://www.humber.com)