

---

# NOTICE TO MARINERS

---

**No. H. 120/2019**

**RIVER HUMBER**

**FH6 LIGHT BUOY – REPLACED**

**MARINERS ARE ADVISED** that the FH6 Light Buoy has been replaced in position:

Latitude: 53° 40.023' N      Longitude: 0° 11.988' W

Characteristics: Fl.R.2s

**MARINERS ARE FURTHER ADVISED** that Notice to Mariners No. H. 117/2019 is hereby cancelled.

**CAPT. A. FIRMAN  
HARBOUR MASTER, HUMBER**

21<sup>st</sup> August 2019

**LOCAL NOTICE TO MARINERS FOR 2014, 2015, 2017, 2018 & 2019 CURRENTLY IN FORCE:**

H. 50/2014, H. 42/2015, H. 158/2017, H. 09/2018, H. 76/2018, H. 87/2018, H.194/2018, H. 02/2019, H. 11/2019,  
H. 18/2019, H. 21/2019, H. 25/2019, H. 27/2019, H. 35/2019, H. 37/2019, H. 44/2019,  
H. 73/2019, H. 75/2019, H. 78/2019, H. 81/2019, **H. 87/2019**, H. 89/2019, H.90/2019, H.93/2019, H.94/2019, H.96/2019, H.104/2019,  
H.109/2019, H.110/2019, H.111/2019, H.113/2019, H.114/2019, H.115/2019, H.116/2019, H.118/2019, H.119/2019.

**THE INTERNET**

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.