
NOTICE TO MARINERS

No. H. 120/2020

RIVER HUMBER

EAST MIDDLE LIGHT BUOY – TEMPORARY REPLACEMENT

MARINERS ARE ADVISED that following repair, the East Middle Light Buoy has been returned to station in its original charted position and the temporary buoy removed.

East Middle Light Buoy

- Position – 53° 44.111' N, 0° 16.525' W (WGS84)
- Light Characteristic – Q.R
- Red Can Buoy

MARINERS ARE FURTHER ADVISED that Notice to Mariners No. H.74/2020 is hereby cancelled.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

26th August 2020

LOCAL NOTICE TO MARINERS FOR 2019 & 2020 CURRENTLY IN FORCE:

H. 18/2019, H. 27/2019, H. 137/2019, H. 138/2019, H. 02/2020, H. 12/2020, H. 20/2020, H. 21/2020, H. 22/2020, H. 25/2020, H. 35/2020, H. 39/2020, H. 40/2020, H. 43/2020, H. 48/2020, H. 49/2020, H. 64/2020, H. 67/2020, H. 68/2020, H. 69/2020, H. 77/2020, H. 79/2020, H. 81/2020, H. 86/2020, H. 88/2020, H. 90/2020, H. 95/2020, H. 98/2020, **H. 99/2020**, H. 100/2020, H. 102/2020, H. 103/2020, H. 111/2020, H. 115/2020, H. 116/2020, H. 117/2020, H. 118/2020, **H. 119/2020**, H. 120/2020.

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com