
NOTICE TO MARINERS

No. H. 128/2020

U P P E R H U M B E R

SHOAL WATER

MARINERS ARE WARNED that surveys carried out on the 7th and 8th September 2020 show the following: -

- 1) A least depth of 0.2 metres **ABOVE** Chart Datum exists North of the ships course 280 metres downstream of the Lower Whitton Light Float.

Deeper water exists on and to the South of the ships course in this vicinity.

- 2) A least depth of 0.2 metres below Chart Datum exists close South of the ships course 70 metres downstream of the No. 32B Light Float.

Deeper water exists on and to the North of the ships course in this vicinity.

- 3) A least depth of 0 metres at Chart Datum exists South of the ships course 235 metres downstream of the No. 32C Light Buoy.

Deeper water exists on and to the North of the ships course in this vicinity.

MARINERS ARE ADVISED that 0 metres at Chart Datum should be used for passage planning purposes and Notice to Mariners No. H.127/2020 is hereby cancelled.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

8th September 2020

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com