
NOTICE TO MARINERS

No. H. 129/2016

RIVER HUMBER

SKITTER CHANNEL – SHOAL WATER

MARINERS ARE WARNED that a survey carried out on the 19th October 2016 shows the following:-

- 1) A least depth of 0 metres at Chart Datum exists 75 metres South of the ships course 985 metres downstream of the No. 21A Light Buoy.

Deeper water exists on and to the North of the ships course in this vicinity.

- 2) A least depth of 0.7 metres below Chart Datum exists 30 metres South of the ships course 830 metres downstream of the No. 21A Light Buoy.

Deeper water exists on and to the North of the ships course in this vicinity.

MARINERS ARE ADVISED that 1.0 metre below Chart Datum should be used for passage planning purposes and Notice to Mariners No. H. 123/2016 is hereby cancelled.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

19th October 2016

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com