
NOTICE TO MARINERS

No. H. 129/2018

R I V E R H U M B E R

HULL – KING GEORGE DOCK REPAIR WORKS

MARINERS ARE ADVISED that fender repair works on the Eastern Approach Jetty to King George Dock, Hull are now complete.

Vessels under 110m LOA can return to making an ebb approach on the Eastern Approach Jetty.

MARINERS ARE REQUESTED to contact the Assistant Dock Master on VHF CH11 prior to transiting the lock.

MARINERS ARE FURTHER ADVISED that Notice to Mariners No. H.78/2018 is hereby cancelled.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

10th August 2018

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com