
NOTICE TO MARINERS

No. H. 135/2016

IMMINGHAM LOCK WESTERN APPROACH JETTY

MARINERS ARE WARNED that the 'Burleigh' wheel on the west side entrance to Immingham lock has been removed for repairs which will take two/three weeks.

Its support frame remains in place and has a large tyre fender positioned horizontally above it.

MARINERS are asked to be aware of this when entering or leaving the lock and manoeuvre with caution.

**Mr. A Swift
DEPUTY HARBOUR MASTER &
PILOTAGE OPERATIONS MANAGER, HUMBER**

10th November 2016

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com