

---

# **NOTICE TO MARINERS**

---

**No. H. 135/2017**

## **RIVER HUMBER**

### **HULL ROADS – EAST MIDDLE - SHOAL WATER**

**MARINERS ARE WARNED** that a survey carried out on the 16<sup>th</sup> October 2017 shows the following: -

- 1) A least depth of 4.5 metres below Chart Datum exists on the Southern edge of the channel 310 metres upstream of the East Middle Light Buoy.

Deeper water exists to the North in this vicinity.

- 2) Depths of between 4.5 metres and 5.5 metres below Chart Datum have encroached up to 30 metres into the Southern edge of the channel from 60 metres upstream of the East Middle Light Buoy to 30 metres downstream of the No. 22 Hook Light Buoy.

Deeper water exists to the North in this vicinity.

**MARINERS ARE ADVISED** that Notice to Mariners No. H. 110/2017 is hereby cancelled.

**CAPT. A. FIRMAN  
HARBOUR MASTER, HUMBER**

18<sup>th</sup> October 2017

**THE INTERNET**

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

[www.humber.com](http://www.humber.com)