

---

# NOTICE TO MARINERS

---

No. H. 143/2018

## HUMBER APPROACHES

### TEMPORARY REPLACEMENT OF SPURN LIGHT FLOAT

**NOTICE IS HEREBY GIVEN** that the Spurn Light Float has been removed for routine maintenance. In its place, a temporary mono-hull Light Float has been deployed which features the same East Cardinal topmark and light characteristics as the Spurn Light Float (Q(3)10s) but no Racon is present.

**CAPT. A. FIRMAN  
HARBOUR MASTER, HUMBER**

6<sup>th</sup> September 2018

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

[www.humber.com](http://www.humber.com)