
NOTICE TO MARINERS

No. H. 144/2017

U P P E R H U M B E R

SHOAL WATER

MARINERS ARE WARNED that surveys carried out on the 7th and 8th November 2017 show the following: -

- 1) A least depth of 0.2 metres **ABOVE** Chart Datum exists close North of the ships course 335 metres downstream of the Lower Whitton Light Float.

Deeper water exists on and to the South of the ships course in this vicinity.

- 2) A least depth of 0.1 metres **ABOVE** Chart Datum exists close South of the ships course 320 metres downstream of the No. 32C Light Buoy.

Deeper water exists on and to the North of the ships course in this vicinity.

- 3) A least depth of 0.3 metres below Chart Datum exists close South of the ships course from 470 metres to 685 metres upstream of the No. 32C Light Buoy.

Deeper water exists on and to the North of the ships course in this vicinity.

- 4) A least depth of 0.3 metres below Chart Datum exists close North of the ships course 175 metres downstream of the No. 34 Light Buoy.

Deeper water exists on the ships course in this vicinity.

MARINERS ARE ADVISED that 0.1 metres below Chart Datum should be used for passage planning purposes and Notice to Mariners No. H. 142/2017 is hereby cancelled.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

8th November 2017

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com