

---

# NOTICE TO MARINERS

---

No. H. 162/2018  
**U P P E R H U M B E R**  
**S H O A L W A T E R**

**MARINERS ARE WARNED** that surveys carried out on the 10<sup>th</sup> and 11<sup>th</sup> October 2018 show the following: -

- 1) A least depth of 1.9 metres **ABOVE** Chart Datum exists close North of the ships course 300 metres downstream of the Lower Whitton Light Float.

Deeper water exists on and to the South of the ships course in this vicinity.

- 2) A least depth of 0.1 metres below Chart Datum exists close North of the ships course 470 metres downstream of the Middle Whitton Light Float.

Deeper water exists on and to the North of the ships course in this vicinity.

- 3) A least depth of 0.1 metres below Chart Datum exists close South of the ships course 140 metres upstream of the Middle Whitton Light Float.  
Deeper water exists on and to the North of the ships course in this vicinity.

- 4) A least depth of 0.1 metres below Chart Datum exists close North of the ships course 530 metres downstream of the No. 33A Light Float.  
Deeper water exists on and to the South of the ships course in this vicinity.

- 5) A least depth of 0.2 metres below Chart Datum exists close South of the ships course from 230 metres upstream and 250 metres downstream of the No. 33A Light Float.  
Deeper water exists on the ships course in this vicinity.

**MARINERS ARE ADVISED** that 0 metres at Chart Datum should be used for passage planning purposes and Notice to Mariners No. H. 161/2018 is hereby cancelled.

**CAPT. A. FIRMAN**  
**HARBOUR MASTER, HUMBER**

11<sup>th</sup> October 2018

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.  
[www.humber.com](http://www.humber.com)