

---

# NOTICE TO MARINERS

---

No. H. 164/2018

## RIVER HUMBER

### NO. 16 SAND END LIGHT FLOAT – TEMPORARY REPLACEMENT

**MARINERS ARE ADVISED** that the No. 16 Sand End Light Float has been replaced with a temporary unmarked red light buoy in position:

Latitude: 53° 42.623' N, Longitude: 0° 14.504 W

Characteristics: Fl R.4s

**MARINERS ARE FURTHER ADVISED** that the temporary buoy will remain in position until further notice and Notice to Mariners H. 163/2018 is hereby cancelled.

**CAPT. A. FIRMAN  
HARBOUR MASTER, HUMBER**

14<sup>th</sup> October 2018

#### THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.