
NOTICE TO MARINERS

No. H. 166/2018

RIVER HUMBER

SKITTER CHANNEL

SHOAL WATER

MARINERS ARE WARNED that surveys carried out on the 15th, 17th and 18th October 2018 show the following: -

A least depth of 0.6 metres below Chart Datum exists close South of the ships course from 230 metres downstream to 150 metres upstream of the No. 20A Light Float.

Deeper water exists on and to the North of the ships course in this vicinity.

**CAPT. A FIRMAN
HARBOUR MASTER, HUMBER**

19th October 2018

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com