
NOTICE TO MARINERS

No. H. 19/2017

U P P E R H U M B E R

S H O A L W A T E R

MARINERS ARE WARNED that a survey carried out on the 14th February 2017 shows the following: -

- 1) A least depth of 0.1 metres **ABOVE** Chart Datum exists close South of the ships course 380 metres upstream of the No. 33A Light Float.

Deeper water exists to the North of the ships course in this vicinity.

- 2) A least depth of 0.1 metres **ABOVE** Chart Datum exists close South of the ships course from 1060 metres to 1370 metres upstream of the No. 34 Light Buoy.

Deeper water exists to the North of the ships course in this vicinity.

MARINERS ARE ADVISED that 0.1 metres **ABOVE** Chart Datum should be used for passage planning purposes. The shoal water referred to in Notice to Mariners No. H. 17/2017 is no longer valid and Notice to Mariners No. H. 08/2017 is hereby cancelled.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

14th February 2017

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners

www.humber.com