

---

# NOTICE TO MARINERS

---

No. H. 32/2017

## U P P E R H U M B E R

### S H O A L W A T E R

**MARINERS ARE WARNED** that surveys carried out on the 15<sup>th</sup> and 16<sup>th</sup> March 2017 show: -

- 1) A least depth of 0.3 metres below Chart Datum exists close South of the ships course 50 metres downstream of the No. 32B Light Float.

Deeper water exists to the North of the ships course in this vicinity.

- 2) A least depth of 0.3 metres below Chart Datum exists on and close North of the ships course from 440 metres to 508 metres upstream of the No. 34 Light Buoy.

Deeper water exists to the North of the ships course in this vicinity.

**MARINERS ARE ADVISED** that 0.1 metres below Chart Datum should be used for passage planning purposes and Notice to Mariners No. H. 27/2017 is hereby cancelled.

**CAPT. A. FIRMAN  
HARBOUR MASTER, HUMBER**

16<sup>th</sup> March 2017

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners

[www.humber.com](http://www.humber.com)