

---

# NOTICE TO MARINERS

---

**No. H. 33/2018**

## R I V E R H U M B E R

### IMMINGHAM ROADS NO. 11A BUOY – DAMAGED AND UNLIT

**MARINERS ARE WARNED** that the No. 11A Buoy is damaged and unlit in position:

Latitude: 53° 38.558' N    Longitude: 0° 10.894' W

Characteristics: Fl(3)G.9s

This will be replaced as soon as it is practicable to do so.

**MARINERS ARE ADVISED** to exercise care and caution when navigating in this vicinity.

**CAPT. A. FIRMAN  
HARBOUR MASTER, HUMBER**

1<sup>st</sup> March 2018

#### THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.