
NOTICE TO MARINERS

No. H. 34/2016

RIVER HUMBER

HUMBER AIDS TO NAVIGATION - TOP MARKS MISSING

MARINERS ARE WARNED that the following Aids to Navigation are missing their top-marks:

1. **Mid New Sand Buoy**
 - a. Latitude: 53° 36.720' N Longitude 0° 21.201' E
 - b. Light Characteristic: Q(9)15s
2. **No 13 Clay Huts Float**
 - a. Latitude: 53° 38.537' N Longitude 0° 11.335' W
 - b. Light Characteristic: Iso.2s

Replacement top-marks will be put in place as soon as circumstances permit.

MARINERS ARE ADVISED to navigate with caution in the vicinity of these Aids to Navigation.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

15 April 2016

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com