
NOTICE TO MARINERS

No. H. 36/2018

R I V E R H U M B E R

NO. 5A BUOY – LIGHT RE-ESTABLISHED

MARINERS ARE ADVISED that the No. 5A Buoy light has been re-established in position:

Latitude: 53° 35.398' N Longitude: 0° 01.978' E

Characteristics: Fl.G.2s

MARINERS ARE FURTHER ADVISED that Notice to Mariners No. H. 34/2018 is hereby cancelled.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

5th March 2018

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.