
NOTICE TO MARINERS

No. H. 37/2018

U P P E R H U M B E R

MOVES OF FLOATING MARKS AND SHOAL WATER

NOTICE IS HEREBY GIVEN that it is proposed on Thursday 8th March 2018 (or as soon after as circumstances permit) to move in order: -

- 1) The No. 33A Light Float to a position 038° T., 837 metres from the Whitton Ness Beacon.

Latitude 53° 43.213 N, Longitude 0° 36.175' W (WGS 84)

(98 metres North North East of its current position)

- 2) The No. 32C Light Buoy to a position 308° T., 1504 metres from the Whitton Ness Beacon.

Latitude 53° 43.356' N, Longitude 0° 37.719' W (WGS 84)

(143 metres North East of its current position)

- 3) The No. 34 Light Buoy to a position 268° T., 1776 metres from the Whitton Ness Beacon.

Latitude 53° 42.819' N, Longitude 0° 38.255' W (WGS 84)

(240 metres North East of its current position)

The No. 33A Light Float will then bear 345° T., 858 metres from the Middle Whitton Light Float and 120° T., 737 metres from the No. 32B Light Float.

The No. 32C Light Buoy will then bear 242° T., 350 metres from the Upper Whitton Light Float.

The No. 34 Light Buoy will then bear 211° T., 1156 metres from the new position of the No. 32C Light Buoy and 055° T., 1440 metres from the No. 40 East Walker Dyke Light.

MARINERS ARE WARNED that on completion of the above moves, the following shoal water will exist: -

- 1) A least depth of 0.2 metres **ABOVE** Chart Datum exists close North of the ships course 320 metres downstream of the Lower Whitton Light Float.

Deeper water exists on the ships course in this vicinity.

- 2) A least depth of 0.2 metres below Chart Datum exists North of the ships course 96 metres upstream of the Cappers West Light Float.

Deeper water exists on the ships course in this vicinity.

- 3) A least depth of 0 metres at Chart Datum exists North of the ships course from 60 to 280 metres downstream of the No. 34 Light Buoy.

Deeper water exists on the ships course in this vicinity.

MARINERS ARE ADVISED that on completion of the above moves 0.2 metres below Chart Datum should be used for passage planning purposes and Notice to Mariners No. H. 35/2018 is will be cancelled.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

6th March 2018

[THE INTERNET](#)

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com