
NOTICE TO MARINERS

No. H. 40/2018

R I V E R H U M B E R

**IMMINGHAM ROADS NO. 11A BUOY – REPLACED
AND LIGHT RE-ESTABLISHED**

MARINERS ARE ADVISED that the No. 11A Buoy has been replaced and the light re-established in position:

Latitude: 53° 38.558' N Longitude: 0° 10.894' W

Characteristics: Fl(3)G.9s

MARINERS ARE FURTHER ADVISED that Notice to Mariners H. 33/2018 is hereby cancelled.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

9th March 2018

LOCAL NOTICE TO MARINERS FOR 2012, 2014, 2015 & 2017 CURRENTLY IN FORCE:

H. 15/2012, H. 50/2014, H. 42/2015, H. 83/2017, H. 94/2017, H. 103/2017, H. 134/2017, H. 146/2017,
H. 149/2017, H. 156/2017, H. 158/2017, H. 163/2017, H. 02/2018, H. 03/2018, H. 08/2018, H. 09/2018,
H. 15/2018, H. 16/2018, H. 20/2018, H. 21/2018, H. 23/2018, H. 25/2018, H. 26/2018, H. 28/2018, H. 29/2018,
H. 31/2018, H. 32/2018, H. 36/2018, H. 37/2018, H. 38/2018, H. 39/2018, H. 40/2018

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.