
NOTICE TO MARINERS

No. H. 42/2017

UPPER HUMBER

SHOAL WATER

MARINERS ARE WARNED that a survey carried out on the 11th April 2017 shows the following: -

- 1) A least depth of 0.1 metres **ABOVE** Chart Datum exists close South of the ships course 230 metres downstream of the Upper Whitton Light Float.

Deeper water exists to the North of the ships course in this vicinity.

- 2) A least depth of 0.1 metres **ABOVE** Chart Datum exists close South of the ships course 470 metres upstream of the No. 32C Light Buoy.

Deeper water exists to the North of the ships course in this vicinity.

- 3) A least depth of 0.3 metres below Chart Datum exists in the navigable channel from 400 metres to 555 metres upstream of the No. 34 Light Buoy.

MARINERS ARE ADVISED that 0.1 metres below Chart Datum should be used for passage planning purposes and the shoal water referred to in Notice to Mariners No. H. 39/2017 is no longer valid.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

11th April 2017

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com