
NOTICE TO MARINERS

No. H. 47/2018

U P P E R H U M B E R

MOVES OF FLOATING MARKS AND SHOAL WATER

NOTICE IS HEREBY GIVEN that it is proposed on Friday 23rd March 2018 (or as soon after as circumstances permit) to move in order: -

- 1) The No. 32B Light Float to a position 356° T., 1124 metres from the Whitton Ness Beacon.

Latitude 53° 43.461' N, Longitude 0° 36.715' W (WGS 84)

(101 metres North North East of its current position)

- 2) The Upper Whitton Light Float to a position 328° T., 1414 metres from the Whitton Ness Beacon.

Latitude 53° 43.504' N, Longitude 0° 37.321' W (WGS 84)

(167 metres North East of its current position)

- 3) The No. 32C Light Buoy to a position 297° T., 1390 metres from the Whitton Ness Beacon.

Latitude 53° 43.194' N, Longitude 0° 37.770' W (WGS 84)

(305 metres South of its current position)

The No. 32B Light Float will then bear 308° T., 752 metres from the No. 33A Light Float.

The Upper Whitton Light Float will then bear 277° T., 671 metres from the new position of the No. 32B Light Float.

The No. 32C Light Buoy will then bear 221° T., 758 metres from the new position of the Upper Whitton Light Float and 037° T., 876 metres from the No. 34 Light Buoy.

MARINERS ARE WARNED that on completion of the above moves, the following shoal water will exist: -

- 1) A least depth of 0.5 metres **ABOVE** Chart Datum exists North of the ships course 310 metres downstream of the Lower Whitton Light Float.

Deeper water exists on the ships course in this vicinity.

- 2) A least depth of 0.5 metres below Chart Datum exists close North of the ships course 60 metres downstream of the Cappers West Light Float.

Deeper water exists on the ships course in this vicinity.

- 3) A least depth of 0.6 metres below Chart Datum exists South of the ships course between the No. 32B Light Float and the Upper Whitton Light Float.

Deeper water exists on the ships course in this vicinity.

- 4) A least depth of 0.4 metres below Chart Datum exists North of the ships course 295 metres downstream of the No. 34 Light Buoy.

Deeper water exists on the ships course in this vicinity.

MARINERS ARE ADVISED that on completion of the above moves 0.2 metres below Chart Datum should be used for passage planning purposes and Notice to Mariners No. H. 46/2018 will be cancelled.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

21st March 2018

[THE INTERNET](#)

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com