
NOTICE TO MARINERS

No. H. 49/2018

HUMBER APPROACHES

HUMBER LIGHT FLOAT – RACON AND AIS RE-ESTABLISHED

MARINERS ARE ADVISED that the Humber Light Float Racon and AIS is re-established in position:

Latitude: 53° 38.700' N Longitude: 0° 21.240' E

Characteristics: LFl.G.10s Racon(T)

MARINERS ARE FURTHER ADVISED that Notice to Mariners H. 43/2018 is hereby cancelled.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

23 March 2018

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.