

---

# **NOTICE TO MARINERS**

---

**No. H. 50/2018**

## **HUMBER APPROACHES**

### **HOTSPUR BUOY – RETURNED TO STATION**

**MARINERS ARE ADVISED** that the Hotspur Buoy has been returned to station in position:

Latitude: 53° 31.898' N    Longitude: 0° 18.295' E

Characteristics: Fl(4).Y.10s

**MARINERS ARE FURTHER ADVISED** that Notice to Mariners H. 45/2018 is hereby cancelled.

**CAPT. A. FIRMAN  
HARBOUR MASTER, HUMBER**

26 March 2018

**LOCAL NOTICE TO MARINERS FOR 2012, 2014, 2015, 2017 & 2018 CURRENTLY IN FORCE:**

H. 15/2012, H. 50/2014, H. 42/2015, H. 83/2017, H. 94/2017, H. 103/2017, H. 134/2017, H. 146/2017,  
H. 149/2017, H. 156/2017, H. 158/2017, H. 163/2017, H. 02/2018, H. 03/2018, H. 08/2018, H. 09/2018,  
H. 15/2018, H. 16/2018, H. 20/2018, H. 21/2018, H. 23/2018, H. 25/2018, H. 26/2018, H. 28/2018, H. 29/2018,  
H. 31/2018, H. 32/2018, H. 36/2018, H. 37/2018, H. 38/2018, H. 39/2018, H. 40/2018, H. 41/2018, H. 42/2018, H. 44/2018,  
H. 46/2018, H. 47/2018, H. 48/2018, H. 49/2018

**THE INTERNET**

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.