
NOTICE TO MARINERS

No. H. 61/2016

RIVER HUMBER

BURCOM DEPOSIT - SHOAL WATER

MARINERS ARE WARNED that a survey carried out on 02 June 2016 shows the following:-

Depths of less than 5.5 metres below Chart Datum have encroached up to 32 metres into the South side of the channel, from 500 metres to 675 metres upstream of the Pyewipe Outfall Light buoy.

Deeper water exists to the North in this vicinity.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

03 June 2016

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com