
NOTICE TO MARINERS

No. H. 63/2016

UPPER HUMBER

SHOAL WATER

MARINERS ARE WARNED that surveys carried out on the 6th and 7th June 2016 show:-

A least depth of 0.3 metres below Chart Datum exists in the navigable channel from the No. 32B Light Float to 545 metres upstream of the No. 32B Light Float.

MARINERS ARE ADVISED that the shoal water referred to in Notice to Mariners No. H. 57/2016 is no longer valid and 0.2 metres below Chart Datum should be used for passage planning purposes.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

7th June 2016

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com