
NOTICE TO MARINERS

No. H. 67/2020

HUMBER APPROACHES

MID NEW SAND BUOY – TEMPORARY REPLACEMENT

NOTICE IS HEREBY GIVEN that on Tuesday 19th May 2020 (or as soon after as circumstances permit), the Mid New Sand Buoy (West Cardinal) will be removed from station for repair and routine maintenance. A Red Can Buoy will be used as a temporary replacement in its charted position until further notice.

Replacement Red Can Buoy

- Position – 53° 36.720'N, 0° 21.201'E (WGS84)
- Light Characteristic – Q.R
- Red Can Buoy
- No Name Board is Present

Removed Cardinal Buoy

- Position – 53° 36.720'N, 0° 21.201'E (WGS84)
- Light Characteristic - Q(9)15s
- YBY West Cardinal Buoy

MARINERS ARE ADVISED to navigate with caution in this vicinity.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

18th May 2020

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.
www.humber.com